



(Above) An experimental loading of Class F-70-7 no. 561095 with cotton bales from the California Cotton Company in 1961. Photographed at Bakersfield, California. (negative N-6268-1, Shasta Division Archives)

(Below) This Missouri Pacific box car has been in an accident and, no longer "Damage Free," is being shipped home on SP Class F-70-7 no. 561786. Photograph in September, 1961. (Howard Ameling)





(Above) This load of machinery parts, noted on the photo as “mining equipment,” was photographed at Tucson, Arizona in September, 1955. Stakes and a few side boards restrain the load. Car no. 142007, Class F-70-7, has all its journal box lids open, perhaps in the process of car inspection prior to departure. (Shasta Division Archives)

(Below) This large vessel for a chemical plant, produced by American Pipe & Construction Company of Portland, Oregon, is being shipped on Class F-70-7 car no. 561824 in this 1959 photo. Note how hold-downs with threaded ends pass through plates and tightened nuts underneath stake pockets. (Sheldon King collection)

